## Combination Photo Tachometer & Stroboscope

## **Features:**

- One battery operated meter performs both Tachometer RPM measurement and Stoboscopic speed and motion analysis.
- Large 0.4" 5 digit LCD digital display.
- Characters on display reverse direction depending on measurement mode you are in.
- Non contact Tachometer measurements of 5 to 100,000 RPM
- Strobe measurements of 100 to 100,000 RPM/FPM.
- Tachometer memory stores last, max and min readings.
- Stoboscope coarse and fine flash rate adjustments in three ranges.
- 0.1% basic accuracy with 0.1 RPM resolution.
- Microprocessor based with quartz crystal oscillator to maintain high accuracy.
- Battery operation brings motion analysis to any location
  Complete with 4-1.5v AA batteries, operation manual and carry case.

Combined Photo/Contact	Tachometer Mode	Stroboscope Mode
Range - RPM:	5-99,999	3 Ranges: 100 - 100,000 FPM/RPM
Accuracy:	±(0.1%rdg+2d)	Range A: 100-1,000
		Range B: 1,000-10,000
		Range C: 10,000-100,000
Sampling Time:	1 Sec ≥ 60 RPM;	<u>-</u>
Resolution:	0.1 RPM (< 1,000 RPM)	0.1 FPM ( < 1,000 FPM)
	1 RPM ( ≥ 1,000 RPM)	1 FPM (≥ 1,000 FPM)
Power:	4x1.5V AA Batteries	<u> </u>
Dimensions:	8.5x2.6x1.5"(215 x 65 x 38 mm)	
Weight:	10.6 oz (300 g)	·



## **Ordering Information**

**461825.....**Combination Tachometer/Stroboscope **461825-NIST**..Combination Tachometer/Stroboscope w/NIST Certificate **461936....**Spare Reflective Tape (23" each roll), 5pks

